



Installation Bracket

Installation Chain


Way of mounting tensioner on the bracket.




Mounting the chain



Free space for turning wheel




Bolts



If the tensioner is mounted on the vertical angle and the bolt goes through the track, use a trackbolt (DOCO:14010)

14010 use:  ø9

Spring tension



Remove pin. The hole should be 20-30 mm below the bracket.

